



- Add 2 STEM labs
- Add strings classroom
- Add secure entry vestibule
- Upgrade technology connectivity
- Improve and identify existing site accessibility
- Replace roof
- Add ADA parking and resurface existing parking lot
- Add additional card access controls
- Upgrade security cameras (to be done by A ISD security department)
- Repair/replace and upgrade heating and A/C, fire alarms, plumbing, interior finishes, exterior, landscaping, playground and site lighting
- Replace K-pod (kindergarten building) heating and A/C, flooring and roof

	LBL Architects
	Phillips/May Corporation

*This report includes highlights of projects. The list is not comprehensive and is subject to mo*